

Certificate

Inspection of the welding quality requirements according ISO 3834

Certificate no.: 01 240 E/A-20 4422

Name and address of the
manufacturer:

Manufacturas Vilassar, S.L. (MAIVISA)
Pol. Ind. Vallmorena II
C/ Serra Vallmorena , 8-10
08339 Vilassar de Dalt (Barcelona)

It is hereby certified that the manufacturer has furnished proof of the comprehensive quality requirements according to the test basis. The mentioned company

- operates a quality system which ensures that the manufacture and inspection of the products stated in our report, are in compliance with applicable technical standards and regulations;
- employs qualified supervisory and inspection personnel;
- has qualified welding processes and welding personnel;
- has adequate facilities permitting manufacture and inspection of welded products.

Specifications:

EN ISO 3834-2

Scope:

The scope of the inspection and other relevant data are given in the annex to the certificate.

Manufacturing Plant:

Manufacturas Vilassar, S.L. (MAIVISA)
Pol. Ind. Vallmorena II
C/ Serra Vallmorena , 8-10
08339 Vilassar de Dalt (Barcelona)


Test Report no.:

92668759.11

Valid until:

December 28, 2023

Cologne, December 29 , 2020


i.A. Eng. Achim Makowka
Certification Body for Manufacturer Qualification



TÜV Rheinland Industrie Service GmbH
Certification Body for Manufacturer Qualification
Am Grauen Stein, D-51105 Köln

M-012-E-Zert-3834-2-Rev-224